



NOTE: STARTING AT THE GATE, USE THE 25' STRING LINE AND STEP 12' TO MARK A PANEL POINT USING SPRAY PAINT, POWDER OR FLAGS WILL GIVE YOU ESTABLISHED POINTS AS A GUIDE LINE.

50' ROUND PEN EXCAVATION AREA

(MINIMUM EXCAVATION AREA IS 50'-0" x 50'-0")