



NOTE: STARTING AT THE GATE, USE THE 20' STRING LINE AND STEP 12' TO MARK A PANEL POINT USING SPRAY PAINT, POWDER OR FLAGS WILL GIVE YOU ESTABLISHED POINTS AS A GUIDE LINE.

40' ROUND PEN EXCAVATION AREA

(MINIMUM EXCAVATION AREA IS 40'-0" x 40'-0")