



NOTE: STARTING AT THE GATE, USE THE 30' STRING LINE AND STEP 12' TO MARK A PANEL POINT USING SPRAY PAINT, POWDER OR FLAGS WILL GIVE YOU ESTABLISHED POINTS AS A GUIDE LINE.

## 60' ROUND PEN EXCAVATION AREA

(MINIMUM EXCAVATION AREA IS 60'-0" x 60'-0")